

2621-130 Ridgepoint Drive, Austin, Texas 78754 512/928-8905

14 January 1988

RECLIVED

Mr. Steve Jenkins
Director of Environmental Engineering
CITY HALL
630 E. Hopkins
San Marcos, TX 78666

JAN 20 1988

ENVIRO MENT & ENGINEERING DIVISION

-CENTER

Dear Mr. Jenkins:

This is in response to your request for clarification of PCB analytical results on sample 18419, which was received at AQUALAB INC. June 14, 1985.

No PCB's were detected in this sample. The detection limits given on the report were established on our gas chromatograph according to EPA method 608, organochlorine pesticides and PCB's. It is our policy to provide actual detection limits rather than "ND" for not detected, when possible. Although we did not see any PCB's in your sample, we reported instrument detection limits at the time of the analysis.

I hope this answers your question adequately.

Please call me if you need additional information.

Sincerely, AQUALAB INC.

Pamela S. Jupe - Manager Austin Division

Pamela Juge

PSJ/rc

90067216

SUPERFUND FILE

DEC 0 2 1992

REORGANIZED

